

# CONTROLS WAREHOUSE


## FUEL OIL METERS

### Controls Warehouse 4 and 8 Bronze Body Oil Meters


Pressure loss curves and application list

#### Pressure Loss

Controls Warehouse CW4—1/8" Oil Meter



Controls Warehouse CW8—1/4" Oil Meter



#### Application List

- #2 Fuel Oil (Diesel Fuel)
- Freon 113
- Freon 12
- Light Oils  
(more than 35 ssu or less than 90 ssu)
- Gasoline
- Jet Fuel (JP-4)
- No Wintergreen (No Lubricity)
- No Acrylic Acid
- No Deionized Water
- No Hydrogen Peroxide
- No Acids
- No Water & Oil
- No Sodium Hydroxide (Caustic Soda)

#### CONTROLS WAREHOUSE

356 Cypress Road, Ocala, Florida 34472; [\(352\)687-2025](tel:(352)687-2025); [sales@controlswarehouse.net](mailto:sales@controlswarehouse.net);  
[controlswarehouse.net](http://controlswarehouse.net); ©11/10/2021 Controls Warehouse, Inc.; all rights reserved